



**Workshop**  
for *Women*

"Building Your Home Improvement Skills"

# Workshop News

*"Building Your Home Improvement Skills"*

## Sprinkler Head Troubleshooting

**Did you know that the majority of your sprinkler system problems are caused by an issue with your sprinkler heads?**

### Announcements

**NOW ON DVD!**

**Finally Fixing That Hole**

**(Drywall Repair)**

Available Now!

[Preview Here](#)

Order your copy today!

Call 303-284-6354

**New Class!**

**Old Faithful in Your Backyard? (Sprinkler Repair)**

**Tuesday May 8th  
Saturday May 19th  
Tuesday May 22nd**

[Register Today](#)

[May 2007 Schedule](#)

### Special Events

**HONOR A WOMEN For Mother's Day!**

Are you looking for a unique gift for that your mother, sister, wife or friend? How about making a donation to Habitat for Humanity and Women Build with an Honor a Woman Card?

[MORE INFO \(CLICK HERE\)](#)

Problem	Possible Cause	Solution
Individual Sprinkler Head is not watering far enough	Insufficient Water Supply	Increase water supply to sprinkler nozzle. Using a small slotted screwdriver turn the slotted screw located on top of the sprinkler head counter-clockwise until the water supply is increased to desired level. (Figure #1)
Individual Sprinkler Head is watering too far.	Excess Water Supply	Decrease water supply to sprinkler nozzle. Using a small slotted screwdriver turn the slotted screw located on top of the sprinkler head clockwise until the water supply is reduced to desired level. (Figure #1)
Individual Sprinkler head is not spraying in the correct pattern	Sprinkler Head Nozzle is blocked	Clean out sprinkler head nozzle. Turn off zone and remove nozzle from the top of the sprinkle head by unscrewing. Check for any debris that may be blocking the slots in the
	Sprinkler Head Nozzle is broken	Replace the Nozzle. Replacement nozzles can typically be purchased where sprinkler heads are sold. (Figure #2)
	Incorrect pattern	Your sprinkler head may have been replaced with a different pattern head. Look for the marks indicating the type of pattern. Replace head if necessary. (Figure #3)
	Incorrect pattern setting on adjustable sprinkler heads	Adjust setting of the pattern according to sprinkler head manufacturers instructions.

Figure # 1





Figure # 2



Figure # 3 1/4 Pattern



1/2 Pattern